



Milliken and Company, Bury, Lancashire

Case Study

Milliken and Company Limited wanted to ensure that their effluent containment bund would not allow any leakage into the groundwater as part of their continuing commitment to protecting the environment.

They asked their Facilities Maintenance Contractor, Don King Services Limited, to research and then carry out the works to the high standards that they insist on.

Don King called in **NCC** to advise on the selection of the most suitable protective, watertight systems for the project. **NCC** recommended and supplied Sika's Poxitar F epoxy combination coating to provide the protection – an advanced coating system, that will even cure underwater. To seal the joints in the concrete and block containment bund, **NCC** recommended and supplied Sikaflex PRO 3WF, a chemically resistant polyurethane joint sealant, which was gunned and tooled into place after the coating works.

To fully support both Milliken and Company and their contractor, **NCC** also provided their Site Supervision Service to ensure the works were executed exactly to specification and in accordance with the manufacturer Sika's recommendations.

Client:

Milliken and Company Limited

Specialist Contractor:

Don King Services Ltd

Products Used:

Sika Ltd

Contact:

BasementWaterproofingSite

01257 266696

www.basementwaterproofingsite.co.uk